

1/8

FIG.1





FIG.2



2/8

FIG.3





FIG.4



High Speed Optical Modulator
Corning Incorporated SP02-196
Walter M. Douglas 34,510
607-974-2431

3/8

FIG.5





FIG.6



High Speed Optical Modulator
Corning Incorporated SP02-196
Walter M. Douglas 34,510
607-974-2431

4/8

FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D





FIG. 7E



5/8

FIG.8A




FIG.8B





FIG.9



6/8

FIG.10





FIG.11



7/8

FIG.12





FIG.13



High Speed Optical Modulator
Corning Incorporated SP02-196
Walter M. Douglas 34,510
607-974-2431

8/8

FIG. 14

